

The second auto crash was said to have occurred at the Fidiwo axis along the Lagos-Ibadan Expressway when two Toyota Sienna vehicles rammed into each other.

The vehicles were said to be travelling in opposite directions when the incident occurred at a section of the road where traffic had been diverted to a single lane due to ongoing construction work.

The silver Toyota Sienna with number plate LSD 226 CK, travelling from Ibadan, was said to have suffered a brake failure and the driver rammed it into the oncoming blue one with number plate AGL 554 EA.

Two female passengers in the Sienna were said to have died, while two others were injured.