Thursday, November 8th, 2012 3:19 PM About Us

Advertise with Us

Send your article here

Contact Us

TRENDING: Trending#1 Trending#2 Trending#3 Trending#4



Latest **Stories**



Oshiomhole, Airhiavbere take battle to Appeal Court



Governor Amaechi backs Indigenship in Rivers State



Uniport to resume Lectures November

Home News & Reports

Special Reports Editorial International

Photo News

Catholic Church Collapses in Nnewi Killing 3, Injuring Others





Related





1 sur 9 08/11/12 15:25



Abia: CAEI Empowerment Programme Members Accuse LG Coordinator of Extortion



Mrs Orji Extends humanitarian hands into talent



Uduaghan Directs
Students in Flooded
Communities Not Be
Left Out Of NECO
and WAEC Exams



The Church

Another Sunday has come with its customary blood trail.

A Roman Catholic Church in Ezinifite Nnewi South collapsed amidst church meeting following a Church service this morning – instantly killing three and injuring others. The worshippers at St. Thomas Catholic Church in Ezinifite saw their church building collapse during Church service.

The church is saod to be under re-construction.

Confirming the incident to 247ureports.com was the President General [PG] Emeritus of the town, Dr. Barthy Okafor. The PG stated that the step mother to Chief Leo Okoye were among the dead. The identities of the other two dead persons are not known.

Stay tuned